

# Certificate

## Inspection of the welding quality requirements according ISO 3834

Certificate no.: 01 240 644/A-19 B027.01

Name and address of the  
certificate holder: **Silica Verfahrenstechnik GmbH**  
**Wittestr. 24**  
**13509 Berlin**  
**Germany**

It is hereby certified that the manufacturer has furnished proof of the quality requirements according to the test basis. The mentioned company:

- operates a quality system which ensures that the manufacture and inspection of the products stated in our report, are in compliance with applicable technical standards and regulations;
- employs qualified supervisory and inspection personnel;
- has qualified welding processes and welding personnel;
- has adequate facilities permitting manufacture and inspection of welded products.

Test basis: **EN ISO 3834-2**


Audit report no.: 01 240 644/A-19 B027 P26


Scope: **The scope of the inspection and other relevant data are given in the annex to the certificate.**

Manufacturing plant: see certificate holder

Validity: **The certificate is valid until 2028-05-31.**

Cologne, 2026-05-25

  
Dipl.-Ing. Achim Makowka  
Certification Body for welding manufacturers



TÜV Rheinland Industrie Service GmbH  
Certification Body for welding manufacturers  
Am Grauen Stein, D-51105 Cologne

M-012-Rev24